




BANGALORE NORTH CITY CORPORATION

DEPUTY HEALTH OFFICER, ZONE-2, ,MEI LAYOUT,BAGALAGUNTE
HESARAGHATTA MAIN ROAD, BANGALORE-560073



NO: BNCC/DHO/ZONE-2/PR/01/26-27

Date: 06-04-2026

SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

It is certified that an inspection team headed by Senior Health Inspector Ward No.14-BBMP have inspected the **NURTURE INTERNATIONAL SCHOOL, No.14/3, 9TH MILE STONE, HESARAGHATTA ROAD, BANGALORE-560073** on 06-04-2026 and found at the time of inspection that **NURTURE INTERNATIONAL SCHOOL,** has safe drinking water facilities for the students and members of staff of the institution and are maintaining the hygienic sanitation, condition, in the school building and the campus there are Separate toilet to facilities Boys and Girls as per the norms prescribed by the State Government

The above is valid for a period of - 1 year


Signature With Seal
Name: Dr. Supendra.R
Designation: Deputy Health Officer
ಬೆಂಗಳೂರು ನಗರ ಪಾಲಿಕೆ
ಯು.ಪಿ.ಎಸ್. ವಲಯ

To,

NURTURE INTERNATIONAL SCHOOL
No.14/3, 9TH MILE STONE, HESARAGHATTA ROAD
BANGALORE-560073.